

Inspection Date	Inspection Type	Inspection SubType	Inspection ID
2023-11-30	Risk Management Inspection	Re-inspection	0000392908

INSPECTION REPORT

Name of Establishment		Owner / Agents Name	
Main Unit: Next Gen EduCare Subunit: Next Gen EduCare - Childcare, Facility Based Subunit ID: 0000302982		Report Discussed With: Nik Report Sent To: nikolas@ngeducare.ca Delivery Method: Email	
Site Address	Rural Address	Mailing Address	
261 - 200 Southridge Drive Okotoks AB T1S 0B2 Canada		261 - 200 Southridge Drive Okotoks AB T1S 0B2 Canada	

Opening Comments

Re-Inspection. Onsite with Nik.

Compliance Record

Closing Comments

Washroom stall modifications completed. Extra cabinet placed in secondary diapering area. Washer and dryer installed. New soap dispensers fully installed.

No violations noted. Recommended for childcare licensing.

Inspection Actions Taken:

- No Action Required
- Violations Corrected

Should you have any questions regarding this report, you can get in touch with me using the contact information below.

Ian Ostrowski

Public Health Inspector

ian.Ostrowski@albertahealthservices.ca

Contact Safe Healthy Environments at 1-833-476-4743 or [submit a request online at ahs.ca/eph.](#)

Child care, food, personal services, and pool inspection reports are now available online at [ahs.ca/inspections.](#)

Inspection Date	Inspection Type	Inspection SubType	Inspection ID
2023-11-23	Initial Inspection	Proactive Assessment	0000390346

INSPECTION REPORT

Name of Establishment		Owner / Agents Name	
Main Unit: Next Gen EduCare Subunit: Next Gen EduCare - Playground, Playgrounds/Play Areas - SCF Subunit ID: 0000303008		Report Discussed With: Nik Report Sent To: nikolas@ngeducare.ca Delivery Method: Email	
Site Address	Rural Address	Mailing Address	
261 - 200 Southridge Drive Okotoks AB T1S 0B2 Canada		261 - 200 Southridge Drive Okotoks AB T1S 0B2 Canada	

Opening Comments

Onsite with Nik for initial inspection of play area.

Compliance Record
Closing Comments

Current play structure does not contain elements of potential entrapment or entanglement, all structures are no more than 36" off the ground and surfaced with rubber crumb fall surfacing.
 Strongly recommend covering remaining unsurfaced play area with artificial turf or other temporary material to mitigate fall damage until remaining surfacing is in place.

Inspection Actions Taken:

- No Action Required

Should you have any questions regarding this report, you can get in touch with me using the contact information below.

Ian Ostrowski

Public Health Inspector

Ian.Ostrowski@albertahealthservices.ca

Contact Safe Healthy Environments at 1-833-476-4743 or [submit a request online at ahs.ca/eph.](#)

Child care, food, personal services, and pool inspection reports are now available online at [ahs.ca/inspections.](#)